

UTTER PRECISION, INC.

The Next Generation in Reliability
PO BOX 337 UTICA, NE 68456
402-534-3513 INFO@UPIVIB.COM

Thermography Report

Customer: BSI Property Address: Lincoln, NE

Thermography date: March 2009 Thermographer: OJ Utter

Outdoor temperature: $45 \, ^{\circ}\text{F}$ Indoor temperature: $68 \, ^{\circ}\text{F}$ Temp diff In-Out Δt : $23 \, ^{\circ}\text{F}$

Weather: Overcast

BuildingIntegrity.doc 1(3) 2009-04-21



UTTER PRECISION, INC.

The Next Generation in Reliability
PO BOX 337 UTICA, NE 68456
402-534-3513 INFO@UPIVIB.COM

Captured at: Main Dome Area

Date & Time: 3/20/2009 12:40:50 AM





Comment:

Heating behind the wall shown on the 4th floor between room 321 and 323.

Recommendation:

Inspect the light fixture on that floor for loose connections.





UTTER PRECISION, INC.

The Next Generation in Reliability
PO BOX 337 UTICA, NE 68456
402-534-3513 INFO@UPIVIB.COM

Captured at: West Side of Building- Outside

Date & Time: 3/20/2009 1:39:05 PM





Comment:

Area outside the pool shows leaks are present

Recommendation:

Clean and Reseal as appropriate. Inspect for development of possible mold issue